

AK-SC255 R: Software Update VR02_173

Product Note

Information		Action required		Market	
ſ₩Ī	Technical		FYI only	V	Food Retail
	Commercial	~	Inform customers (Where required)		Commercial Refrigeration OEMs (CRO)
		~	Upgrade instruction attached		Commercial Air Conditioning OEMs (CAO)

Summary New Software is now available VR02_173

VR02_173 replaces VR02_171 and offers updates and fixes (see below table)

Description New 255 Software update

Affected AK-SC255 R version products All versions

Timing Immediate

Updates /

Corrections The table below highlights new features and updates

Defect ID	Synopsis
962232	Photocell fc units an issue in 2.171
962216	XML Interface Systems in Load shed report back with status in XML as Auto Off. Need to indicate state is Load Shed.
962195	Lighting Dimmer Control issue in 2.171 stemming from decimal place update with Lux light level.
962157	XML does not report correct error if same value is written to start/end load shed times.
962155	Load shedding status is not displayed in Win module.

Upgrade instructions





AK-SC255_Upgrade Proceedure.pdf EDF List_171 RESM.pdf

Contact Technical Support:

Stan Blitstein

stanblitstein@danfoss.com Danfoss Baltimore, USA

SAP / Pricing Support:

Ingrid Schmolk

E-mail ingridschmolk@danfoss.com

Danfoss Baltimore, USA

Global Product Manager:

Andrew I Niblock

E-mail: niblock@danfoss.com Danfoss Baltimore, USA

Product Manager: Rainer Mahringer

© Danfoss A/S (ADAP-KOOL®), 2012-07 Lit.No USCO.EN.RFO.M1.22 / 521U0225



E-mail: rainer.maehringer@danfoss.com Danfoss Baltimore, USA