

Synopsis and Enhancements: VR2.231

Add reset for IO task timer not running.

XML Alarm: Change delay in resending alarm without ack being received from 2 seconds to 30 seconds

EDF Work - XML Tags - additional XML Tags needed for Pack Controllers AK-PC781 and 783 for setpoint

Remove possibility of Divide by zero in refrig algo for dewpoint calculation.

ALARM XMIT: if an alarm is set to severe and sent remotely by XML format the severity attribute is incorrect

EDF Work - AK-CC 211 - 084B8519 - v2.4x update

EDF Work - AK-PC781 - 080Z0186 - V4.4x controller version updated

EDF Work - FC-103 - New Version 1.3x

EDF Work - AK-CC750 - 080Z0146 - V6.4 Update - (Spain version)

SLV's - showing incorrect setpoint value on system view of evaporators (Problem with AK-SC255 - R version only)

ALARM; Change timeout on waiting for ACK of alarm sent via XML format

DHCP is unreliable

SqD read interval optimization

FC-103 Support Update - Add drive designations '134L and '134N'

EDF Work - Po Optimization adjustments in MLC codes - revert forced close from 'Refrig' to 'Inactive' (AK-CC550's

EDF Work - New Integrated Pack Controller for new HW platform - AK-PC781 - 080Z0191 v1.0

XML 2.0: Calculation branch of Misc does not properly handle Units of Measurement correctly

EDF Work - OPTYMA Pack Controller - 084B8135 - V1.4x Update (new version update from v1.3x)

EDF Work - AK-PC311 (Old code # for AK-PC840) - 080Z0112 - v1.1, 1.3 for Spain

Unable to change Misc input - 'failed to change value' error message received

EDF Work - AK-CC750 - version 6.4x Update -(080Z0121, 080Z0122, 080Z0125, 080Z0126)

Device Lists - Soon To Exceed Limits In The Total Number Of Device Selections Per Front End.

EDF Work - New controller type "AK-CC 210A" - 084B8530 - v1.02

Dimmer out function not responding

EDF Work - AK-CC550 - New version 1.8x for 084B8030 (and 084B8036 --> 115 volt version)

Recommended Boot Loader version: 6.15

Recommended AKA65 Software version: 5.9