

ENGINEERING
TOMORROW

Danfoss

Installation Guide

iC7 Series Liquid-cooled System Modules

Active Front-End, Grid Converter, Inverter, and DC/DC Converter Modules



drives.danfoss.com |

iC7

Contents

1 Overview

1.1 Safety and Installation Awareness	7
1.2 Checking the Delivery and the Contents	7
1.3 Unpacking the Product	7
1.4 Lifting the System Modules	8
1.5 Lifting the System Modules with Integration Unit	8
1.6 Lifting the Filters	9

2 Mechanical Installation

2.1 Installation Requirements	10
2.2 Installation Directions	10
2.3 Installing System Modules	10
2.3.1 Installing System Modules into a Cabinet Vertically	10
2.3.2 Installing System Modules into a Cabinet Horizontally	11
2.3.3 Installing System Modules into a Cabinet on their Backsides	12
2.4 Installing System Modules with Integration Units	13
2.4.1 Installing System Modules with Integration Units into a Cabinet Vertically	13
2.4.2 Installing System Modules with Integration Units into a Cabinet Horizontally	15
2.4.3 Installing System Modules with Integration Units into a Cabinet on their Backsides	16
2.5 Installing Filters	17
2.5.1 Installing L Filter into a Cabinet, 400 A, 1000 A	17
2.5.2 Installing L Filter into a Cabinet, 1640 A	17

3 Cooling

3.1 Insertion of Pipes into Cooling Circuit Connectors	19
3.2 Inlet and Outlet Connectors	19
3.2.1 Inlet and Outlet Connectors of System Modules	19
3.2.2 Inlet and Outlet Connectors of System Modules with Integration Units	20
3.2.3 Inlet and Outlet Connectors of the L Filter	21
3.3 Cooling Circuit Pipes	21
3.4 Bending the Pipes	22
3.4.1 Bending Pipes in the Air	22
3.4.2 Bending Pipes with a Bending Jig	23

4 Electrical Installation

4.1 Control System of the System Modules	25
4.2 Grounding Principles	25
4.3 Prerequisites for Cable Installation	25
4.4 Recommended Installation of Motor Cables	27
4.5 Installing the Cables	28
4.5.1 Field Cabling Installation	28
4.5.2 Installing the Cables, AFE and GC (AR10L, AR12L)	28
4.5.3 Installing the Cables, INU (IR10L, IR12L)	29
4.5.4 Installing the Cables, DC/DC Converter (DR10L, DR12L)	30
4.5.5 Installing the Cables, INU (IM10L, IM12L), AFE and CG (AM10L, AM12L), and DC/DC Converter (DM10L, DM12L)	31
4.5.6 Installing the Cables with the Power Terminal Adapter, INU IR10L, IR12L	31
4.5.7 Installing the Cables with the Power Terminal Adapter, INU IM10L, IM12L	32
4.6 Installing the DC Fuses to the DC Terminals	33
4.7 Changing the EMC Protection Level	35
4.7.1 Changing the EMC Protection Level, AR10L	35
4.7.2 Changing the EMC Protection Level, AR12L	36
4.7.3 Changing the EMC Protection Level, LC Filter, OF7Z1, 380 A	37
4.7.4 Changing the EMC Protection Level, LC Filter, OF7Z1, 760 A	38
4.8 AuxBus Communication	39
4.8.1 Preparing the AuxBus Cable	39
4.8.2 AuxBus Cabling	40

5 Control Installation

5.1 Assembling the Control Unit Mounting Plates	41
5.2 Attaching the Control Unit Mounting Plates	41
5.3 Installing the Control Unit	42
5.4 Connecting the Fieldbus Cable and the Fiber Cables	42
5.5 Installing the Control Cables into the Control Terminals	43
5.6 Control Board Connections	44
5.7 Star Coupler Board	46
5.8 Star Coupler Board Connections	47
5.9 I/O and Relay Option Connections	48
5.10 Connecting the Control Panel	50
5.11 Installing the microSD Card	50

6 Commissioning

6.1 Commissioning the System Modules	52
6.2 Measuring the Insulation Resistance of the Motor Cable	53
6.3 Measuring the Insulation Resistance of the Mains Cable	53
6.4 Measuring the Insulation Resistance of the Motor	53
6.5 Preparing for a PC Connection	54

7 Specifications

7.1 Tightening Torques	55
7.2 Cable Sizes	55
7.2.1 List of Cable Size Information	55
7.2.2 Field Cable Sizes for AFE and GC Modules, 525–690 V AC	55
7.2.3 Internal Cable Sizes for AFE and GC Modules, 525–690 V AC	57
7.2.4 Field Cable Sizes for INU Module, 525–690 V AC	57
7.2.5 Alternative Cable Sizes for Marine Installations, AFE or GC Modules 525–690 V AC	58
7.2.6 Alternative Cable Sizes for Marine Installations, INU Modules 525–690 V AC	59
7.2.7 Source Cable Sizes for DC/DC Converter Modules, 640–1100 V DC and 640–1200 V DC	61
7.2.8 Cable Sizes for DC-filter Capacitors	61
7.3 Fuses	62
7.3.1 List of Fuse Size Information	62
7.3.2 AC Fuses for AFE or GC 525–690 V AC, IP00/Open Type	62
7.3.3 DC Fuses for AFE or GC 640–1200 V DC, IP00/Open Type	64
7.3.4 DC Fuses for INU 640–1200 V DC, IP00/Open Type	65
7.3.5 DC-bus Fuses for DC/DC Converter, IP00/Open Type	66
7.3.6 Source DC+ Fuses for DC/DC Converter, IP00/Open Type	67
7.3.7 Source DC- Fuses for DC/DC Converter, IP00/Open Type	68

1 Overview

1.1 Safety and Installation Awareness

Before starting installation, read all safety guidelines and precautions related to installing system modules. For more information, see the product-specific design guide. Supplemental information and other guides can be downloaded from <https://www.danfoss.com/en/service-and-support/documentation/>.

1.2 Checking the Delivery and the Contents

Make sure that the items supplied and the information on the product label correspond to the order confirmation.




Figure 1: Product Label for iC7 Series Liquid-cooled System Modules

1	Model code of the product	2	Product number
3	Serial number	4	Power, input, and output ratings for high overload
5	Power, input, and output ratings for low overload	6	Protection rating
7	Temperature ratings for ambient air and coolant	8	Maximum continuous coolant pressure

1.3 Unpacking the Product

The products are packed in cardboard on a wooden pallet.

The system modules and the filters are delivered horizontally. The 400 A L Filter is delivered vertically.

1. Open the package only when installing the product.
2. See the center of gravity in the relevant dimensional drawing in the design guide.
3. See the weight in the design guide.
4. Remove the product from the pallet where it was connected to.
5. If the optional sea container package (+TASE) was ordered, remove the yellow VCI capsule from the product.

1.4 Lifting the System Modules

1. Attach the lifting device in the hole on the top of the system module.
2. If necessary, lift the system module into a vertical position.




Figure 2: Lifting the System Module

3. Lift the system module to the required location.

1.5 Lifting the System Modules with Integration Unit

1. Put the lifting hooks in 4 holes at the top of the system module.




Figure 3: Lifting the System Module with Integration Unit

2. If necessary, lift the system module into a vertical position.

The recommended lifting angle is $60^\circ \pm 15^\circ$.

3. Lift the system module to the required location.

1.6 Lifting the Filters

Use these instructions to lift the L Filter, the LC Filter, the dU/dt Filter, the dU/dt and Common-mode Filter, and the DC/DC Filter.

1. Put the lifting hooks in 4 holes at the top of the filter.
2. If necessary, lift the filter into a vertical position.

The recommended lifting angle is $60^\circ \pm 15^\circ$.




Figure 4: Example: Lifting the L Filter

3. Lift the filter to the required location.

2 Mechanical Installation

2.1 Installation Requirements

The system modules that are described in this guide have the protection rating IP00/Open Type. Install them in a cabinet or other enclosure that has a correct level of protection against the ambient conditions in the installation area.

The installation procedure varies between product categories and mechanical variants depending on selected options.

Reserve enough space around the system module to ensure sufficient cooling. The mounting plane must be relatively even.

2.2 Installation Directions

NOTICE

Do not install the system module upside down or the front side facing down.

The system module can be installed vertically, horizontally, and on its backside.

2.3 Installing System Modules

2.3.1 Installing System Modules into a Cabinet Vertically

1. Install the system module into the cabinet in a vertical position.
2. Use mounting holes to attach the system module into the cabinet.
 - a. Use M6 grade 8.8 screws.
 - b. For an AM12L or IM12L, use M8 grade 8.8 screws for the lower parts.




Figure 5: Mounting Holes of the System Module in Vertical Position

1 Mounting holes

3. Attach the system module to the mounting brackets of the cabinet.

The mounting brackets are not included in the delivery.

- a. To ease the removal of the system module from the cabinet for service, use support bars under the system module.




Figure 6: The Mounting Brackets and the Installation of System Modules into the Cabinet

1	Mounting brackets	2	Support bars
---	-------------------	---	--------------

2.3.2 Installing System Modules into a Cabinet Horizontally

1. Install the system module into the cabinet in a horizontal position on its left side.
2. Use mounting holes to attach the system module into the cabinet.
 - a. Use M6 grade 8.8 screws.
 - b. For an AM12L or IM12L, use M8 grade 8.8 screws for the lower parts.




Figure 7: Mounting Holes of the System Module in Horizontal Position

1	Mounting holes	2	View from the front
3	View from the bottom		

3. Attach the system module to the mounting brackets of the cabinet.

The mounting brackets are not included in the delivery.

2.3.3 Installing System Modules into a Cabinet on their Backsides

1. Install the system module into the cabinet on its backside.
2. Use mounting holes to attach the system module into the cabinet.
 - a. Use M6 grade 8.8 screws.
 - b. For an AM12L or IM12L, use M8 grade 8.8 screws for the lower parts.




Figure 8: Mounting Holes of the System Module on its Backside

1	Mounting holes	2	View from the side
3	View from the bottom		

3. Attach the system module to the mounting brackets of the cabinet.

The mounting brackets are not included in the delivery.

2.4 Installing System Modules with Integration Units

2.4.1 Installing System Modules with Integration Units into a Cabinet Vertically

1. Install the system module into the cabinet in a vertical position.
2. Use mounting holes to attach the system module into the cabinet.
 - a. For aluminum parts, use M6 grade 8.8 screws with a thread depth of 6–14 mm (0.24–0.55in), and a tightening torque of 6–8 Nm (53–71 in-lb).
 - b. For sheet metal parts, use M5 (DIN 7500) screws with a maximum thread depth of 20 mm (0.78 in), and a tightening torque of 3–4 Nm (27–35 in-lb).




Figure 9: Mounting Holes of the System Module, AFE with the Integration Unit

1 Mounting holes in aluminum parts

2 Mounting holes in sheet metal parts

3. Attach the system module to the mounting brackets of the cabinet.

The mounting brackets are not included in the delivery.




Figure 10: The Mounting Brackets and the Installation of System Modules with the Integration Unit into the Cabinet

1 Mounting brackets

2.4.2 Installing System Modules with Integration Units into a Cabinet Horizontally

1. Install the system module into the cabinet in a horizontal position on its left side.
2. Use mounting holes to attach the system module into the cabinet.
 - a. For aluminum parts, use M8 grade 8.8 screws with a thread depth of 6–14 mm (0.24–0.55in), and a tightening torque of 6–8 Nm (53–71 in-lb).
 - b. For sheet metal parts, use M5 (DIN 7500) screws with a maximum thread depth of 20 mm (0.78 in), and a tightening torque of 3–4 Nm (27–35 in-lb).




Figure 11: Mounting Holes of the System Module with the Integration Unit in Horizontal Position

1	Mounting holes	2	View from the front
3	View from the bottom		

3. Attach the system module to the mounting brackets of the cabinet.

The mounting brackets are not included in the delivery.

2.4.3 Installing System Modules with Integration Units into a Cabinet on their Backsides

1. Install the system module into the cabinet on its backside.
2. Use mounting holes to attach the system module into the cabinet.
 - a. For aluminum parts, use M6 grade 8.8 screws with a thread depth of 6–14 mm (0.24–0.55in), and a tightening torque of 6–8 Nm (53–71 in-lb).
 - b. For sheet metal parts, use M5 (DIN 7500) screws with a maximum thread depth of 20 mm (0.78 in), and a tightening torque of 3–4 Nm (27–35 in-lb).




Figure 12: Mounting Holes of the System Module with the Integration Unit on its Backside

- | | | | |
|---|----------------|---|----------------------|
| 1 | Mounting holes | 2 | View from the bottom |
|---|----------------|---|----------------------|

3. Attach the system module to the mounting brackets of the cabinet.

The mounting brackets are not included in the delivery.

2.5 Installing Filters

2.5.1 Installing L Filter into a Cabinet, 400 A, 1000 A

1. Install the filter into the cabinet in a vertical position.
2. Align the filter so that the pins of the filter fit into the square holes at the back wall of the cabinet.




Figure 13: Installing the L Filter into a Cabinet (400 A, 1000 A)


- | | | | |
|---|----------------------------------|---|-------------------------------|
| 1 | Square mounting holes | 2 | The mounting holes at the top |
| 3 | The mounting holes at the bottom | | |

3. Use the mounting holes to attach the filter.
 - a. Attach the filter from all the corners: top front, top back, bottom front, and bottom back.

The mounting brackets are not included in the delivery.

2.5.2 Installing L Filter into a Cabinet, 1640 A

1. Install the filter into the cabinet in a vertical position.
2. Use the mounting holes to attach the filter.
 - a. Attach the filter from all the corners: top front, top back, bottom front, and bottom back.



e30bl376.10

Figure 14: Installing the L Filter into a Cabinet (1640 A)

- | | | | |
|---|----------------------------------|---|-------------|
| 1 | The mounting holes at the top | 2 | The bracket |
| 3 | The mounting holes at the bottom | | |

3. Use the bracket to attach the filter from below.

The mounting brackets are not included in the delivery.

3 Cooling

3.1 Insertion of Pipes into Cooling Circuit Connectors

The insertion length of a $\varnothing 16$ mm (0.63 in) pipe is 29 mm (1.14 in). Make a mark on the pipe where it can be checked that the pipe is correctly inserted into the cooling circuit connector.

To remove the pipe from the connector, push the release sleeve towards the connector and pull out the pipe.

For cold PA11 plastic pipes, the minimum bending radius is 138 mm (5.43 in). A smaller bending radius requires heating of the pipe. See [3.3 Cooling Circuit Pipes](#).




Figure 15: Inserting a Pipe into the Cooling Circuit Connector, mm (in)

1	The pipe ferrule	2	The pipe ferrule inside the pipe
3	A cooling circuit connector (available as option)	4	The mark in the pipe
5	The release sleeve		

3.2 Inlet and Outlet Connectors

3.2.1 Inlet and Outlet Connectors of System Modules

NOTICE

INCORRECT INLET AND OUTLET CONNECTIONS IN THE COOLING SYSTEM

If inlet and outlet connectors are connected incorrectly, the cooling does not work as expected. Incorrect cooling can damage the product.

- Make the connections carefully.




Figure 16: Inlet Connectors of IM10L (left) and IM12L (right)

1 Inlet connectors




Figure 17: Outlet Connectors of IM10L (left) and IM12L (right)

1 Outlet connectors

3.2.2 Inlet and Outlet Connectors of System Modules with Integration Units




Figure 18: Inlet and Outlet Connectors of IR10L (left) and IR12L (right)

1 Inlet connector

2 Outlet connector




Figure 19: Optional Outlet Connectors of IR10L (left) and IR12L (right)

1 Optional outlet connector

3.2.3 Inlet and Outlet Connectors of the L Filter




Figure 20: Inlet and Outlet Connectors of the L Filter

1 Inlet/outlet connector

2 Inlet/outlet connector

3.3 Cooling Circuit Pipes

The pipes used in the cooling circuit are PA11 plastic pipes with a diameter of $\varnothing 16/13$ mm (0.63/0.51 in) (Rilsan model code BESNOP40TL).

There are 2 ways to make permanent bends to the pipes.

- The quickest and easiest way is to make the bend in the air by bending it by hand. Do this if only 1 bend is needed and the dimensions do not matter, or the dimension can be adjusted by cutting the pipe after bending.
- If multiple precise pipes with several bends are needed, it is recommended to use a bending jig. There are commercial jigs on the market (for example, Eiskoffer Bending Kit from Alphacool), but the jig can be also self-made from plywood or some other easy-to-work material. But the material must be able to withstand at least 200 °C (392 °F).

Required tools for bending the pipes:

- Gloves
- Adjustable heat gun
- Round silicone rubber cord
 - Ø12–12.5 mm (0.47–0.49 in)
 - Solid
 - Hardness: minimum 60 Shore A, recommended >70 Shore A

Recommended tools for bending the pipes:

- Water bucket or sink
- Distilled water
- Bending jig

NOTICE

OVERHEATING OF THE PIPES

If the pipe is overheated, the wall thickness and pressure resistance change, and the shape of the pipe collapses easily.

- Do not heat the pipes above 180 °C (356 °F).

NOTICE

UNEVEN HEATING OF THE PIPES

If the pipe is heated unevenly or over a too small area, it wrinkles easily when the pipe is bent. The wall strength and pressure resistance at the wrinkled point is uncertain.

- Before bending the pipes, heat the pipes evenly and over the whole bending area.

3.4 Bending the Pipes

3.4.1 Bending Pipes in the Air

1. Insert the silicon cord into the pipe and to the bending location.

It is recommended that the pipe end is at least 5 cm (2 in) from the bending area. If the bending area is too close to the pipe end, the pipe end can become oval, which can cause the pipe and fitting joint to leak.

It is recommended to moisten the cord with distilled water to make it easier to insert into the pipe.

The cord is inserted into the pipe before it is heated, to produce equal counter pressure and to prevent the tube from buckling. The hard pipe is easy to bend evenly with the cord inside.

2. Set the heat gun upright on the table and set the temperature to 350 °C (662 °F).

Make sure that the heat gun does not fall down.

3. Slowly move the pipe back and forth while rotating it over the heat gun.

The aim is to heat the pipe evenly over the entire bending area to around 150–170 °C (302–338 °F). Examples of heating times:

- o When making a simple L-bend, a suitable heating time is approximately 2 minutes for a distance of 5–10 cm (2–4 in).
- o When making a U-bend, the heating time is approximately 4 minutes for 15–20 cm (6–8 in).

Beware of overheating. If the pipe temperature rises above 180 °C (356 °F), it starts to melt, and the wall thickness can change. As the temperature of the pipe approaches the melting point, the pipe changes color from cloudy to clear, and starts to smell burned.

4. Once the tube is heated all around the bending area, bend it to the desired shape.

The recommended minimum bending radius >30 mm (1.18 in).

5. Hold the pipe in the desired position and cool it quickly, for example, in a sink or under a tap.

➡ If the pipe was heated enough, the bending is permanent.

6. Pull the cord out of the pipe. If the bend is steep, it can be necessary to open the bend slightly to get out the cord.
7. After bending the pipe, check the circularity of the pipe ends.

A Ø16/13 mm (0.63/0.51 in) tube ferrule (for example, 1827-16-13 from Parker) can be inserted into the pipe as an aid to assess the circularity of the pipe.

3.4.2 Bending Pipes with a Bending Jig

These instructions were prepared with the Eiskoffer bending kit from Alphacool, but other commercial or self-made jigs can also be used.

1. Prepare the bending jig.
2. Insert the silicon cord in to the pipe and to the bending location.

It is recommended that the pipe end is at least 5 cm (2 in) from the bending area. If the bending area is too close to the pipe end, the pipe end can become oval, which can cause the pipe and fitting joint to leak.

It is recommended to moisten the cord with distilled water to make it easier to insert into the pipe.

The cord is inserted into the pipe before it is heated, to produce equal counter pressure and to prevent the tube from buckling. The hard pipe is easy to bend evenly with the cord inside.

3. With the cord inside, bend the pipe to the jig.

The recommended minimum bending radius >30 mm (1.18 in).




Figure 21: Pipe Bending Jig Example

1	Pipe	2	Silicon cord
3	Pipe holders	4	Bending wheel

- Set the heat gun temperature to 200 °C (392 °F).
- Slowly move the heat gun back and forth over the entire bending area.

The aim is to heat the pipe evenly over the entire bending area to around 150–170 °C (302–338 °F). When the pipe is heated only at the outer edge, it takes time to heat the inner edge of the pipe as well. Therefore, the temperature used is fairly low and, for example, when making a 180° bend with radius Ø32 mm (Ø1.26 in), the suitable heating time is 10 minutes.

Beware of overheating. If the pipe temperature rises above 180 °C (356 °F), it starts to melt, and the wall thickness can change. As the temperature of the pipe approaches the melting point, the pipe changes color from cloudy to clear, and starts to smell burned.

- Before removing the pipe from the jig, let it cool completely. The cooling takes more than 10 minutes.

To accelerate the cooling process, submerge the jig and pipe in water.

- Once the pipe has cooled, remove it from the jig.

➡ If the pipe was heated enough, the bending is permanent.


- Pull the cord out of the pipe. If the bend is steep, it can be necessary to open the bend slightly to get out the cord.
- After bending the pipe, check the circularity of the pipe ends.

A Ø16/13 mm (0.63/0.51 in) tube ferrule (for example, 1827-16-13 from Parker) can be inserted into the pipe as an aid to assess the circularity of the pipe.

An alternative way to use the bending jig is to preheat the pipes as advised in [3.4.1 Bending Pipes in the Air](#), and then fold them into the jig and let them cool down.

4 Electrical Installation

4.1 Control System of the System Modules



e30b1521.10

Figure 22: Example of a Control System of an AFE Module

4.2 Grounding Principles

Ground the AC drive in accordance with applicable standards and directives.

According to IEC 60364-5-54; 543.1, unless local wiring regulations state otherwise, the cross-sectional area of the protective grounding conductor must be at least $\frac{1}{2}$ times of the phase conductor and made of the same material when the phase conductor cross-section is above 35 mm^2 (AWG 2).


The connection must be fixed.

4.3 Prerequisites for Cable Installation

Table 1: Minimum Distances from Motor Cables to Other Cables

Distance to other cables [m (ft)]	Length of the shielded motor cable [m (ft)]
0.3 (1.0)	≤ 50 (164)
1.0 (3.3)	≤ 150 (492)

1. Before starting, make sure that none of the components of the AC drive is live. Read all safety precautions in this guide and other documents available for this product.
2. Make sure that the motor cables are sufficiently far from other cables.
3. The motor cables must go across other cables at an angle of 90°.
4. If it is possible, do not put the motor cables in long parallel lines with other cables.
5. If the motor cables are in parallel with other cables, obey the minimum distances (see [Table 1](#)).
6. The distances are also valid between the motor cables and the signal cables of other systems.
7. The maximum length of shielded motor cables is 150 m (492 ft). If the used motor cables are longer, contact the vendor to get more information. The motor cable length is based on the maximum number of cables for each frame. For example, the 590 A INU module is based on 3 parallel cables, and the 880 A INU module on 4 parallel cables. The default motor cable operating capacitance is 0.75 nF/m. If some other cable type is used or the number of cables connected in parallel does not match with recommendations, the maximum motor cable length must be derated so that the maximum total motor cable capacitance is not exceeded.
 - a. Default maximum motor cable setup for IM11: $4 \times (3 \times 120 + 70) \text{ mm}^2$, 150 m, 0.75 nF/m → $CTOT = 4 \times 150 \text{ m} \times 0.75 \text{ nF/m} = 450 \text{ nF} = CMAX$
 - b. Example where number of motor cables connected in parallel is higher than the default: $6 \times (3 \times 120 + 70) \text{ mm}^2$, 100 m, 0.75 nF/m → $CTOT = 6 \times 100 \text{ m} \times 0.75 \text{ nF/m} = 450 \text{ nF} = CMAX$
 - c. Example where motor cable capacitance is higher than the default: $4 \times (3 \times 120 + 70) \text{ mm}^2$, 130 m, 0.85 nF/m → $CTOT = 4 \times 130 \text{ m} \times 0.85 \text{ nF/m} = 442 \text{ nF} < CMAX$
8. The maximum cable length of the filters is also 150 m (492 ft).
9. Only use symmetrical and shielded motor cables.
10. Use symmetrical power cabling with power units connected in parallel. Each power unit must have the same number of cables with an equal cross-section and equal length.
11. Perform the cable insulation checks if necessary.



e30bg434.11

Figure 23: Cabling Principle

1	Grounding bar of the control cable	2	Control cable
3	Grounding conductor	4	Mains cables
5	Motor cables	6	Strain relief
7	The grounding clamp, 360° grounding		

4.4 Recommended Installation of Motor Cables

If the power units are connected in parallel without output filters or only with a common-mode filter, the recommended common coupling point of motor cables is at the motor terminals. It is also possible to use an alternative installation method where the common coupling point of the motor cables is near the drives. In this case, to avoid current imbalance, the installation must be symmetrical and the tolerance of cable length (impedance) to common coupling point is maximum 5%. If the cable connections are not symmetrical, use a dU/dt filter or a sine-wave filter.




Figure 24: Recommended Installation

1	Inverter module	2	Common coupling point at the motor terminals
---	-----------------	---	--




Figure 25: Alternative Installation Method

1	Inverter module
---	-----------------

4.5 Installing the Cables

4.5.1 Field Cabling Installation

The field cabling terminals are not included in the delivery of the system module. Install field cabling to the appropriate terminals. Connect the terminals of the AFE/GC to the LCL Filter terminals with internal cables or busbars. Define the size of the internal cables or busbars according to the nominal current of the drive, and according to local regulations.

4.5.2 Installing the Cables, AFE and GC (AR10L, AR12L)

1. Find the mains terminals in the lower part of the system module. Notice the location of the L1, L2, and L3 terminals.




Figure 26: The Mains Terminals and Grounding Terminal of AFE and GC, AR10L (left) and AR12L (right)

1	Mains terminal L1	2	Mains terminal L2
3	Mains terminal L3	4	Grounding terminal

2. Connect the mains cables to the corresponding mains terminals.

See the bolt sizes in [7.2.1 List of Cable Size Information](#).

See the correct tightening torques in [7.1 Tightening Torques](#).

4.5.3 Installing the Cables, INU (IR10L, IR12L)

1. Find the motor terminals in the lower part of the system module. Notice the location of the U, V, and W terminals.




Figure 27: The Motor Terminals and the Grounding Terminal of INU, IR10L (left) and IR12L (right)

1	Motor terminal U	2	Motor terminal V
3	Motor terminal W	4	Grounding terminal

2. Connect the motor cables to the corresponding motor terminals.

See the bolt sizes in [7.2.1 List of Cable Size Information](#).

See the correct tightening torques in [7.1 Tightening Torques](#).

The terminal bolt spacing is 48 mm (1.89 in).

4.5.4 Installing the Cables, DC/DC Converter (DR10L, DR12L)

1. Find the DC and grounding terminals in the lower part of the system module.




Figure 28: The DC and Grounding Terminals of DC/DC Converter, DR10L (left) and DR12L (right)

1	+ terminal (source DC+)	2	DC- connection point for DC source to filter capacitor
3	Grounding terminal		

2. Connect the DC cables to the terminals.

See the bolt sizes in [7.2.1 List of Cable Size Information](#).

See the correct tightening torques in [7.1 Tightening Torques](#).

The terminal bolt spacing is 48 mm (1.89 in).

To optimize the performance of the DC-filter capacitor, make sure that the wire between the capacitor and the DC bus is as short as possible.

4.5.5 Installing the Cables, INU (IM10L, IM12L), AFE and CG (AM10L, AM12L), and DC/DC Converter (DM10L, DM12L)

1. Find the power terminals below the system module. Notice the location of the different terminals.




Figure 29: The Power Terminals of IM10L, AM10L, and DM10L (left) and IM12L, AM12L, and DM12L (right)

1	Grounding terminal	2	Motor terminal U (IM10L), mains terminal L1 (AM10L), or DC terminal U (DM10L)
3	Motor terminal V (IM10L), mains terminal L2 (AM10L), or DC terminal V (DM10L)	4	Motor terminal W (IM10L), mains terminal L3 (AM10L), or DC terminal W (DM10L)
5	Cable lugs and heat-shrink tubes		

2. Attach the cable lugs to the cables.
3. Put heat-shrink tubes around the cable lugs and shrink them.
4. Install the cable lugs to the corresponding motor terminals with washers and nuts.

See the bolt sizes in [7.2.1 List of Cable Size Information](#).

See the correct tightening torques in [7.1 Tightening Torques](#).

The terminal bolt spacing is 48 mm (1.89 in).

4.5.6 Installing the Cables with the Power Terminal Adapter, INU IR10L, IR12L

Use this procedure to install cables when more than 2 smaller power cables are preferred, for example in marine installations. See [7.2.6 Alternative Cable Sizes for Marine Installations, INU Modules 525–690 V AC](#).

One power terminal adapter (+AFMC) is needed for IR10L, and 2 adapters for IR12L.

Procedure

1. Install a power terminal adapter first to the lowest terminal W/T3.




Figure 30: Installing Power Terminal Adapters to the Terminals, and Cables to the Power Terminal Adapter, Example of IR10L

1	Power terminal adapter	2	Motor cables
---	------------------------	---	--------------

2. Use M10 pressure balancing washers SFS 3738, M10 conical spring washers DIN 6796, and M10 grade 8 hex nuts DIN 934.
3. Tighten the nuts to 40 Nm (354 in-lb).
4. Install the motor cables to the lowest terminal.
5. Use M8 pressure balancing washers SFS 3738, M8 conical spring washers DIN 6796, and M8 grade 8 hex nuts DIN 934.
6. Tighten the nuts to 20 Nm (177 in-lb).
7. Repeat the steps 2–6 for the middle terminal V/T2.
8. Repeat the steps 2–6 for the uppermost terminal U/T1.

4.5.7 Installing the Cables with the Power Terminal Adapter, INU IM10L, IM12L

Use this procedure to install cables when more than 2 smaller power cables are preferred, for example in marine installations. See [7.2.6 Alternative Cable Sizes for Marine Installations, INU Modules 525–690 V AC](#).

One power terminal adapter (+AFMC) is needed for IM10L, and 2 adapters for IM12L.

Procedure

1. Install a power terminal adapter first to the lowest terminal.




Figure 31: Installing Power Terminal Adapters to the Terminals, and Cables to the Power Terminal Adapter, Example of IM10L

1	Power terminal adapter	2	Motor cables
---	------------------------	---	--------------

2. Use M10 pressure balancing washers SFS 3738, M10 conical spring washers DIN 6796, and M10 grade 8 hex nuts DIN 934.
3. Tighten the nuts to 40 Nm (354 in-lb).
4. Install the motor cables to the lowest terminal.
5. Use M8 pressure balancing washers SFS 3738, M8 conical spring washers DIN 6796, and M8 grade 8 hex nuts DIN 934.
6. Tighten the nuts to 20 Nm (177 in-lb).
7. Repeat the steps 2–6 for the middle terminal.
8. Repeat the steps 2–6 for the uppermost terminal.

4.6 Installing the DC Fuses to the DC Terminals

Use these instructions to install the DC fuses. The DC fuses are available as option +AKFX or +AKFF.

1. Attach busbars to the DC fuses. Make sure that the visual indicator (the red dot) of the DC fuse is facing forward.
 - a. Screw the stud on the fuse. Make sure that the stud is inserted as far as it goes. The maximum tightening torque is 15 Nm (133 in-lb).
 - b. Place the busbar on the stud.
 - c. Mount the busbar with an M12 nut and washers, and tighten to torque 45 Nm (398 in-lb).

NOTICE

If the busbars on the DC fuses are not aligned, they can strain the fuse structure and break it over time. When tightening the screws, make sure that the busbars stay aligned.




Figure 32: Installing Busbars to the DC Fuses

1	M12 nut	2	M12 spring washer
3	M12 washer	4	Busbar
5	Stud	6	Fuse
7	Visual indicator		

2. Attach DC-terminal busbars to the DC terminals of the system modules.

Use Combi M8 screws.

Use the tightening torque 20 Nm (177 in-lb).




Figure 33: Installing DC-terminal Busbars to the DC Terminals

3. Attach the DC fuse assemblies to the DC-terminal busbars and to the common DC busbars.

Use M10 screws and washers.

Use the tightening torque 35–40 Nm (310–354 in-lb).

The common DC busbars are not included in the delivery.




Figure 34: Installing DC Fuse Assemblies

4.7 Changing the EMC Protection Level

4.7.1 Changing the EMC Protection Level, AR10L

In an IT system, to change the EMC protection level of the AC drive from C3 to C4, disconnect the LC Filter ground capacitor.

Procedure

1. Loosen the screw of the grounding wire of the LC Filter.
2. Remove the grounding wire from the grounding terminal.
3. Move the cable lug of the grounding wire with the screw onto the insulator and tighten the screw (maximum 0.5 Nm (4.4 in-lb)).





Figure 35: Level C3



e30bh791.1

Figure 36: Level C4


4. After the change, write "The EMC level was changed from C3 to C4", and the date on the "product modified" label. If the label is not yet attached, attach it on the drive near the product label.

4.7.2 Changing the EMC Protection Level, AR12L

In an IT system, to change the EMC protection level of the AC drive from C3 to C4, disconnect the LC Filter ground capacitor.


Procedure

1. Loosen the screw of the grounding wire of the LC Filter.
2. Remove the grounding wire from the grounding terminal.
3. Move the cable lug of the grounding wire with the screw onto the insulator and tighten the screw (maximum 0.5 Nm (4.4 in-lb)).



e30bg862.10

Figure 37: Level C3



e30bh792.1

Figure 38: Level C4


4. After the change, write "The EMC level was changed from C3 to C4", and the date on the "product modified" label. If the label is not yet attached, attach it on the drive near the product label.

4.7.3 Changing the EMC Protection Level, LC Filter, OF7Z1, 380 A

In an IT system, to change the EMC protection level of the AC drive from C3 to C4, disconnect the LC Filter ground capacitor.

Procedure

1. Loosen the screw of the grounding wire of the LC Filter.
2. Remove the grounding wire from the grounding terminal.
3. Move the cable lug of the grounding wire with the screw onto the insulator and tighten the screw (maximum 0.5 Nm (4.4 in-lb)).



e30bh793.1

Figure 39: Level C3




Figure 40: Level C4

4. After the change, write "The EMC level was changed from C3 to C4", and the date on the "product modified" label. If the label is not yet attached, attach it on the drive near the product label.

4.7.4 Changing the EMC Protection Level, LC Filter, OF7Z1, 760 A

In an IT system, to change the EMC protection level of the AC drive from C3 to C4, disconnect the LC Filter ground capacitor.

Procedure

1. Loosen the screw of the grounding wire of the LC Filter.
2. Remove the grounding wire from the grounding terminal.
3. Move the cable lug of the grounding wire with the screw onto the insulator and tighten the screw (maximum 0.5 Nm (4.4 in-lb)).




Figure 41: Level C3




Figure 42: Level C4

4. After the change, write "The EMC level was changed from C3 to C4", and the date on the "product modified" label. If the label is not yet attached, attach it on the drive near the product label.

4.8 AuxBus Communication

4.8.1 Preparing the AuxBus Cable

An AuxBus cable is included in the delivery. If the AuxBus cable was ordered as a loose option (a 10-meter cable), use these instructions.

1. Cut the cable to the required length.
2. To reveal the wires, strip the cable for 50 mm (1.97 in) at both ends.
 - a. For the frame designation AR10L, strip the cable for 90 mm (3.54 in).
3. At 1 end of the cable, remove approximately 15 mm (0.59 in) of the insulation of the cable.
4. Strip the wires 7 mm (0.28 in).




Figure 43: The Ready AuxBus Cable

- | | |
|------------------|---------|
| 1 Terminals | 2 Wires |
| 3 Shield removed | |

4.8.2 AuxBus Cabling

1. Connect the AuxBus cable between the filter and the power unit. If there are several power units and filters, connect each filter to the power units individually.
 - a. Connect the end of the AuxBus cable where the insulation was removed to terminal X79 on the power unit.
 - b. Connect the other end of the AuxBus cable to terminal X86 on the filter.

Use the tightening torque 0.22–0.25 Nm (1.9–2.2 in-lb).

2. Route the cable so that there is no risk of getting in touch with bare busbars or terminals.
3. Ground each AuxBus cable at 1 end, at the X79 terminal. To make the grounding connection, attach the shield of the cable to the frame with a cable clamp.

The lower part of the cable clamp fixes the cable to the plate and provides strain relief. The upper part provides ~360° grounding for the cable shield.




Figure 44: Grounding of the AuxBus Cable

- | | |
|------------------|---------------|
| 1 Shield removed | 2 Cable clamp |
|------------------|---------------|


4. At the terminal X86 end of the cable, place the cable in a cable clamp for strain relief.

5 Control Installation

5.1 Assembling the Control Unit Mounting Plates

Use these instructions to assemble the mounting plate of the modular control unit. All the parts can be found in the accessories bag.

1. Assemble the mounting plate as shown in the illustration.
 - a. Attach the base grounding plate into the mounting plate.
 - b. Align the cable clamps in the holes in a wave-like form and attach with screws.
 - c. Attach the grounding plate extension onto the base grounding plate with 2 screws.
 - d. Attach the cable clamps with screws.



e30b1520.10

Figure 45: Assembling the Mounting Plate

5.2 Attaching the Control Unit Mounting Plates

Use these instructions to attach 2 or several mounting plates to each other, and to install mounting plates to the cabinet. All the parts can be found in the accessories bag.

1. Install the mounting plates to each other by fitting the sides together.




Figure 46: Attaching Mounting Plates to Each Other

1 Lip

2. Attach the mounting plates onto the cabinet with screws by the 4 mounting holes in the corners of the mounting plates.


The screws are not included in the delivery. Use an M4/M5 screw.

5.3 Installing the Control Unit

Install the control unit to the selected location. Use the 4 mounting holes in the corners of the mounting plate.

5.4 Connecting the Fieldbus Cable and the Fiber Cables

1. Connect the PLC to the Ethernet port X1 or X2 in the control board with a fieldbus cable.
2. Connect the terminal X80 in the control board to the terminal X90 in the star coupler board with a fiber cable.
3. Connect the terminals X301–X316 in the star coupler board to the power units with fiber cables.



e30b1522.10


Figure 47: Connecting the Fieldbus Cable and the Fiber Cables

1	PLC (not included in the delivery)	2	Fieldbus cable
3	Control board	4	Star coupler board
5	Fiber cables	6	Power units

5.5 Installing the Control Cables into the Control Terminals

1. Install the control cables into the control terminals.

See the pin numbering of the I/O and Relay Option in [5.9 I/O and Relay Option Connections](#).



e30b1031.11

Figure 48: Example of Installing the Control Cables

- | | | | |
|---|------------------|---|-------------|
| 1 | Control cable | 2 | Cable clamp |
| 3 | Grounding plates | | |

2. Strip the control cables. Attach the control cables to the cable clamps on the suitable grounding plate.

The lower part of the cable clamp fixes the cable to the plate and provides strain relief. The upper part provides ~360° grounding for the cable shield.




Figure 49: Stripping the Cable and Using the Grounding Plates

- | | | | |
|---|----------------------------------|---|---------------|
| 1 | Stripping length, 10 mm (0.4 in) | 2 | Strain relief |
| 3 | Grounding | | |

5.6 Control Board Connections

Table 2: Control Board Connections

Terminal	Function	Connector type
X1	Ethernet port (used for fieldbus)	RJ45
X2	Ethernet port (used for fieldbus)	RJ45
X0	Ethernet port (used for the PC tool)	RJ45
Micro SD	microSD card	Micro SD
X62	24 V DC supply	2 x 3 spring force connector 0.2–1.5 mm ²
X33 for inverter module	STO terminal	1 x 10 spring force connector 0.2–1.5 mm ²
Option bus	Option bus (internal connection)	Custom
X80	Fiber optic link to power unit or star coupler board	LC-duplex
X9	Control panel terminal	iX Industrial
RTC battery	RTC battery	BR1632 (battery type)




Figure 50: Control Board Terminal Block and Terminal Numbering

A	Status indicators (FAULT, WARN, READY)	B	Fieldbus indicators (ST, X1, X2) and Ethernet port indicators (X0)
1	Control panel connector (X9)	2	Fiber optic link to power unit (X80)
3	24 V DC supply (X62)	4	microSD card
5	RTC battery holder	6	Ethernet port (X0)
7	Ethernet port (X1)	8	Ethernet port (X2)

Table 3: STO Terminal Signals (X33) for the Inverter Module

Terminal	Function	Description
41A ⁽¹⁾	24 V	+ 24 V DC Output
41B ⁽¹⁾	24 V	+ 24 V DC Output
42	S.INA+	+ Safe Input Channel A
43	S.INB+	+ Safe Input Channel B
44	S.FB+	+ STO Feedback
45A ⁽¹⁾	GND	0 V/GND
45B ⁽¹⁾	GND	0 V/GND
46	S.INA-	- Safe Input Channel A

Table 3: STO Terminal Signals (X33) for the Inverter Module (continued)

Terminal	Function	Description
47	S.INB-	- Safe Input Channel B
48	S.FB-	- STO Feedback

1) Terminals 41A, 41B, 45A, and 45B have double pins to make connections easier.

Table 4: 24 V DC Supply Signals (X62)

Terminal	Function	Description
101	+24 V input	Internal +24 V DC, 60 W control supply
102	GND	Power supply ground
61	+24 V external input	External +24 V DC control supply, maximum 10 A. Must be fuse-protected. Possible to daisy chain for multiple controllers.
62	GND	Power supply ground
63	+24 V output	+24 V DC output for daisy chain, only available when the +24 V DC external input control supply is used.
64	GND	Power supply ground

For the circuit diagrams of the control unit, see the product-specific design guide.

5.7 Star Coupler Board

The star coupler board can be installed next to the control unit. The star coupler board can also be installed near the power units to make the cabling from the star coupler board to the power units easier.




Figure 51: The Star Coupler Board with 16 Ports

1	Board configuration status indicator	2	+24 V power status indicator
3	Power unit connection status indicators	4	Fiber connection to the power unit (X301–X316)
5	+24 V power supply (X65)	6	Fiber connection to the control board (X90)
7	Control link status indicator	8	Ethernet speed indicator
9	Ethernet link activity indicator	10	Ethernet port (X7)

5.8 Star Coupler Board Connections

Table 5: Star Coupler Board Connections

Terminal	Function	Connector type
X7	Ethernet port	RJ45
X65	24 V DC supply	2 x spring force connector 2.5 mm ²
X90	Fiber optic link to control board	LC-duplex
X301–X316	Fiber optic link to power unit	LC-duplex

Table 6: 24 V DC Supply Signals (X65)

Terminal	Function	Description
61	+24 V external input	External +24 V DC star coupler supply, maximum 10 A. Must be fuse-protected.
62	GND	Power supply ground

5.9 I/O and Relay Option Connections




Figure 52: I/O and Relay Option Terminal Block and Terminal Numbering

Table 7: I/O and Relay Option Signals

Terminal	Function	Connector type
X13	I/O terminal	2 x 11 spring force connector 0.2–1.5 mm ²
X51	Thermistor input	1 x 2 spring force connector 0.25–2.5 mm ²
X101	Relay 1	1 x 3 spring force connector 0.25–2.5 mm ²
X102	Relay 2	1 x 3 spring force connector 0.25–2.5 mm ²
X103	Relay 3	1 x 2 spring force connector 0.25–2.5 mm ²

Table 8: I/O Terminal Signals (X13)

Terminal	Function
11	+24 V _{out}
12	+24 V _{out}
13	DI 1
14	DI 2
15	DI 3
16	DI 4
17	DI 5
18	DI 6

Table 8: I/O Terminal Signals (X13) (continued)

Terminal	Function
19	DGND
20	DGND
21	DO 1
22	DO 2
23	GND
24	GND
31	AO 1
32	+10 V ref.
33	AI 1
34	AI 2
35	GND
36	GND
37	GND
38	GND

Table 9: Thermistor Input Signals (X51)

Terminal	Function	Description
71	TI+	Thermistor input, galvanically isolated. $R_{trip} = 4\text{ k}\Omega$
72	TI-	

Table 10: Relay 1 Signals (X101)

Terminal	Function	Description
1	COM	Configurable relay output. Switching capacity: <ul style="list-style-type: none"> • 24 V DC/8 A • 250 V AC/8 A • 125 V DC/0.4 A Minimum switching load: 5 V/10 mA
2	NO	
3	NC	

Table 11: Relay 2 Signals (X102)

Terminal	Function	Description
4	COM	Configurable relay output. Switching capacity: • 24 V DC/8 A • 250 V AC/8 A • 125 V DC/0.4 A Minimum switching load: 5 V/10 mA
5	NO	
6	NC	

Table 12: Relay 3 Signals (X103)

Terminal	Function	Description
7	COM	Configurable relay output. Switching capacity: • 24 V DC/8 A • 250 V AC/8 A • 125 V DC/0.4 A Minimum switching load: 5 V/10 mA
8	NO	

5.10 Connecting the Control Panel

1. Connect the control panel to the terminal X9 in the modular control unit with a panel cable adapter.

5.11 Installing the microSD Card

Supported microSD card types:

- SD
- SDHC
- SDXC

The microSD card must be formatted for the file system FAT32. It is recommended to use SDHC type cards as they are preformatted to FAT32.

1. Locate the microSD card hole on the control board of the control unit.




Figure 53: Location of the microSD Card

1 The microSD card

2. Push the new microSD card into the hole.

The contact area must face the text μ SD on the right.

To remove the microSD card, push it. The microSD card pops out.

6 Commissioning

6.1 Commissioning the System Modules

Follow these instructions to commission the drive.

Read the safety instructions in the Safety Guide and obey them.

1. Make sure that the device connected to the drive output is installed correctly.
2. Make sure that the drive and the device connected to the drive output are grounded.
3. Make sure to select the mains cable and the output cables correctly.

For information on cable selections, see [7.2.1 List of Cable Size Information](#).

4. Make sure that the control cables are as far as possible from the power cables.
5. Make sure that the shields of the shielded cables are connected to a grounding terminal that is identified with the grounding symbol.
6. Do a check of the tightening torques of all the terminals.
7. Make sure that the cables do not touch the electrical components of the drive.
8. Make sure that the common input +24 V is connected to an external power source.
9. Make sure that the digital input ground is connected to your digital system ground when floating, or to the control terminal ground.
10. Check that the coolant inlets and outlets are connected according to instructions.
11. Open the shut-off valves.
12. Check the quality and quantity of the coolant.
13. Make sure that the liquid circulation system operates correctly.
14. Make sure that there is no condensation on the surfaces of the drive.
15. Make sure that there are no unwanted objects in the installation space.
16. Before connecting the drive to mains, check the installation and the condition of all the fuses and other protective devices.

For information on fuse selections, see [7.3.1 List of Fuse Size Information](#).

17. Perform the insulation checks.
18. Check the status of the LED indicators of the control board, star coupler board, and power unit.

NOTICE

PRE-CHARGING NEEDED

The system modules do not have an internal DC-link charging circuit. If the drive is connected to the supply voltage without first pre-charging the DC-link capacitors, the inrush current can damage the equipment.

- Before closing the main switch and connecting the drive to mains, pre-charge the DC-link capacitors of the system modules.
- See the application guide for details.

NOTICE**DC/DC CONVERTER PRE-CHARGING**

If the DC source is connected to the DC/DC converter without first pre-charging the DC filter capacitors, the inrush current can damage the equipment.

- Before connecting the DC source to the DC/DC converter, power on the DC/DC converter and pre-charge the DC filter capacitors to the same voltage as the DC source.
- See the iC7 Series DC/DC Converter Application Guide for details.

6.2 Measuring the Insulation Resistance of the Motor Cable

Use these instructions to check the insulation of the motor cable.

The AC drive is already measured at the factory.

1. Disconnect the motor cable from the terminals U, V, and W, and from the motor.
2. Measure the insulation resistance of the motor cable between phase conductors 1 and 2, between phase conductors 1 and 3, and between phase conductors 2 and 3.
3. Measure the insulation resistance between each phase conductor and the grounding conductor.
4. The insulation resistance must be $>1\text{ M}\Omega$ at the ambient temperature of $20\text{ }^{\circ}\text{C}$ ($68\text{ }^{\circ}\text{F}$).

6.3 Measuring the Insulation Resistance of the Mains Cable

Use these instructions to check the insulation of the mains cable.

The AC drive is already measured at the factory.

1. Disconnect the mains cable from the terminals L1, L2, and L3, and from mains.
2. Measure the insulation resistance of the mains cable between phase conductors 1 and 2, between phase conductors 1 and 3, and between phase conductors 2 and 3.
3. Measure the insulation resistance between each phase conductor and the grounding conductor.
4. The insulation resistance must be $>1\text{ M}\Omega$ at the ambient temperature of $20\text{ }^{\circ}\text{C}$ ($68\text{ }^{\circ}\text{F}$).

6.4 Measuring the Insulation Resistance of the Motor

Use these instructions to check the insulation of the motor.

The AC drive is already measured at the factory.

NOTICE

Obey the instructions of the motor manufacturer.


1. Disconnect the motor cable from the motor.
2. Open the bridging connections in the motor connection box.
3. Measure the insulation resistance of each motor winding. The voltage must be the same or higher than the motor nominal voltage, but at least 1000 V .
4. The insulation resistance must be $>1\text{ M}\Omega$ at the ambient temperature of $20\text{ }^{\circ}\text{C}$ ($68\text{ }^{\circ}\text{F}$).
5. Connect the motor cables to the motor.
6. Do the final insulation check on the drive side. Put all phases together and measure to the ground.
7. Connect the motor cables to the drive.

6.5 Preparing for a PC Connection

Use these instructions to connect the drive or several drives to a PC with an RJ45 cable.

1. Connect an RJ45 cable to the PC.

To connect several drives at the same time, use an Ethernet switch between the PC and the control unit.



1 Ethernet switch

Figure 54: Connecting the Drive to a PC

2. Connect the cable coming from the PC or from the Ethernet switch to the Ethernet port X0 on the control unit of the drive.
3. See the Application Guide for information on the next steps.

7 Specifications

7.1 Tightening Torques

Table 13: Tightening Torques and Bolt Lengths of the Terminals

Bolt	Tightening torque [Nm]	Maximum length of bolt under the busbar [mm]	Tightening torque [in-lb]	Maximum length of bolt under the busbar [in]
M4	2–2.5	–	18–22	–
M5	3–4	–	27–35	–
M6	6–9	–	53–80	–
M8	17–20	10	150–177	0.39
M10	35–40	22	310–354	0.87
M12	65–70	22	575–620	0.87
Grounding bolt (M8)	17–20	20	150–177	0.79

Table 14: Tightening Torques of Fuses

Fuse size	Tightening torque [Nm]	Tightening torque [in-lb]	Stud maximum torque [Nm]	Stud maximum torque [in-lb]	Stud	Bolt
31	13.5 +0/-2	119 +0/-17	10	88	M8x30 Zn DIN913	–
44	26 +0/-2	230 +0/-17	–	–	–	M10x20 DIN933-8.8-Zn
73	46 +0/-4	407 +0/-35	15	132	M12x35 Zn DIN913	–

7.2 Cable Sizes

7.2.1 List of Cable Size Information

This topic lists the links to find the cable size tables for the system modules.

- [7.2.2 Field Cable Sizes for AFE and GC Modules, 525–690 V AC](#)
- [7.2.3 Internal Cable Sizes for AFE and GC Modules, 525–690 V AC](#)
- [7.2.4 Field Cable Sizes for INU Module, 525–690 V AC](#)
- [7.2.5 Alternative Cable Sizes for Marine Installations, AFE or GC Modules 525–690 V AC](#)
- [7.2.6 Alternative Cable Sizes for Marine Installations, INU Modules 525–690 V AC](#)
- [7.2.7 Source Cable Sizes for DC/DC Converter Modules, 640–1100 V DC and 640–1200 V DC](#)
- [7.2.8 Cable Sizes for DC-filter Capacitors](#)

7.2.2 Field Cable Sizes for AFE and GC Modules, 525–690 V AC

The AFE and GC modules do not have field cabling terminals for mains. Connect the AFE and GC modules to adequate size field cabling terminals or switching device.

Table 15: Field Cable Sizes for AFE and GC Modules, 525–690 V AC

Model code	Frame ⁽¹⁾	Cu [mm ²]	Al [mm ²]
iC7-60SLxx07-236AE00Fx	Ax10L	3x150+70	3x240+72
iC7-60SLxx07-300AE00Fx		3x240+120	2x(3x120+41)
iC7-60SLxx07-334AE00Fx		2x(3x95+50)	2x(3x150+41)
iC7-60SLxx07-380AE00Fx		2x(3x120+70)	2x(3x185+57)
iC7-60SLxx07-425AE00Fx	Ax12L	2x(3x120+70)	2x(3x185+57)
iC7-60SLxx07-475AE00Fx		2x(3x150+70)	2x(3x240+72)
iC7-60SLxx07-530AE00Fx		2x(3x185+70)	3x(3x150+41)
iC7-60SLxx07-595AE00Fx		2x(3x240+120)	3x(3x185+57)
iC7-60SLxx07-670AE00Fx		4x(3x120+70)	4x(3x150+41)
iC7-60SLxx07-760AE00Fx		4x(3x120+70)	4x(3x150+41)
iC7-60SLxx07-850AE00Fx	2 x Ax12L	4x(3x120+70)	4x(3x185+57)
iC7-60SLxx07-945AE00Fx		4x(3x150+70)	4x(3x240+72)
iC7-60SLxx07-1040E00Fx		4x(3x185+95)	6x(3x150+41)
iC7-60SLxx07-1230E00Fx		4x(3x240+120)	6x(3x185+57)
iC7-60SLxx07-1325E00Fx		8x(3x120+70)	8x(3x150+41)
iC7-60SLxx07-1500E00Fx		8x(3x120+70)	8x(3x150+41)
iC7-60SLxx07-1700E00Fx	3 x Ax12L	6x(3x185+95)	9x(3x150+41)
iC7-60SLxx07-1800E00Fx		6x(3x240+120)	9x(3x185+57)
iC7-60SLxx07-2000E00Fx		6x(3x240+120)	9x(3x240+72)
iC7-60SLxx07-2250E00Fx		12x(3x120+70)	9x(3x240+72)
iC7-60SLxx07-2500E00Fx	4 x Ax12L	8x(3x240+120)	12x(3x185+57)
iC7-60SLxx07-2650E00Fx		12x(3x150+70)	12x(3x240+72)
iC7-60SLxx07-2940E00Fx		12x(3x150+70)	12x(3x240+72)
iC7-60SLxx07-3120E00Fx	5 x Ax12L	10x(3x240+120)	15x(3x185+57)
iC7-60SLxx07-3600E00Fx		15x(3x150+70)	15x(3x240+72)
iC7-60SLxx07-3900E00Fx	6 x Ax12L	18x(3x150+70)	18x(3x240+72)
iC7-60SLxx07-4320E00Fx		18x(3x150+70)	18x(3x240+72)
iC7-60SLxx07-4750E00Fx	7 x Ax12L	21x(3x150+70)	21x(3x240+72)
iC7-60SLxx07-5040E00Fx		21x(3x150+70)	21x(3x240+72)
iC7-60SLxx07-5400E00Fx	8 x Ax12L	24x(3x150+70)	24x(3x240+72)
iC7-60SLxx07-5750E00Fx		24x(3x150+70)	24x(3x240+72)

1) AM10L, AR10L, AM12L, or AR12L

7.2.3 Internal Cable Sizes for AFE and GC Modules, 525–690 V AC

Table 16: Bolt Sizes for the AFE and GC Modules

Frame ⁽¹⁾	Bolt size for internal cable or busbar	Number of grounding terminals/bolt size
Ax10L	M10	1/M8
Ax12L	M10	1/M8
2 x Ax12L	M10	2/M8
3 x Ax12L	M10	3/M8
4 x Ax12L	M10	4/M8
5 x Ax12L	M10	5/M8
6 x Ax12L	M10	6/M8
7 x Ax12L	M10	7/M8
8 x Ax12L	M10	8/M8

1) AM10L, AR10L, AM12L, or AR12L

7.2.4 Field Cable Sizes for INU Module, 525–690 V AC

Table 17: Field Cable Sizes for INU Module, 525–690 V AC

Model code	Frame ⁽¹⁾	Motor cable Cu [mm ²]	Motor cable Al [mm ²]
iC7-60SLIN07-170E00Fx	1x10L	3x120+70	3x185+57
iC7-60SLIN07-261E00Fx		3x185+95	2x(3x95+29)
iC7-60SLIN07-325E00Fx		3x240+120	2x(3x120+41)
iC7-60SLIN07-365E00Fx		2x(3x95+50)	2x(3x150+41)
iC7-60SLIN07-416E00Fx		2x(3x120+70)	2x(3x185+57)
iC7-60SLIN07-465E00Fx	1x12L	2x(3x150+70)	2x(3x240+72)
iC7-60SLIN07-525E00Fx		2x(3x185+95)	3x(3x150+41)
iC7-60SLIN07-590E00Fx		2x(3x240+120)	3x(3x185+57)
iC7-60SLIN07-650E00Fx		2x(3x240+120)	3x(3x185+57)
iC7-60SLIN07-730E00Fx		3x(3x150+70)	4x(3x150+41)
iC7-60SLIN07-820E00Fx		4x(3x120+70)	4x(3x185+57)
iC7-60SLIN07-945E00Fx	2 x 1x12L	4x(3x150+70)	4x(3x240+72)
iC7-60SLIN07-1060E00Fx		4x(3x185+95)	6x(3x150+41)
iC7-60SLIN07-1230E00Fx		4x(3x240+120)	6x(3x185+57)
iC7-60SLIN07-1400E00Fx		4x(3x240+120)	8x(3x150+41)
iC7-60SLIN07-1500E00Fx		8x(3x120+70)	8x(3x150+41)
iC7-60SLIN07-1640E00Fx		8x(3x120+70)	8x(3x185+57)

Table 17: Field Cable Sizes for INU Module, 525–690 V AC (continued)

Model code	Frame ⁽¹⁾	Motor cable Cu [mm ²]	Motor cable Al [mm ²]
iC7-60SLIN07-1795E00Fx	3 x lx12L	9x(3x120+70)	9x(3x185+57)
iC7-60SLIN07-2080E00Fx		9x(3x150+70)	12x(3x150+41)
iC7-60SLIN07-2300E00Fx		12x(3x120+70)	12x(3x150+41)
iC7-60SLIN07-2460E00Fx		12x(3x120+70)	12x(3x185+57)
iC7-60SLIN07-2830E00Fx	4 x lx12L	12x(3x150+70)	16x(3x150+41)
iC7-60SLIN07-3050E00Fx		16x(3x120+70)	16x(3x185+57)
iC7-60SLIN07-3260E00Fx		16x(3x120+70)	16x(3x185+57)
iC7-60SLIN07-3500E00Fx	5 x lx12L	15x(3x150+70)	20x(3x150+41)
iC7-60SLIN07-4035E00Fx		20x(3x120+70)	20x(3x185+57)
iC7-60SLIN07-4400E00Fx	6 x lx12L	18x(3x150+70)	24x(3x150+41)
iC7-60SLIN07-4850E00Fx		24x(3x120+70)	24x(3x185+57)
iC7-60SLIN07-5300E00Fx	7 x lx12L	28x(3x120+70)	28x(3x150+41)
iC7-60SLIN07-5600E00Fx		28x(3x120+70)	28x(3x185+57)
iC7-60SLIN07-6100E00Fx	8 x lx12L	32x(3x120+70)	32x(3x185+57)
iC7-60SLIN07-6400E00Fx		32x(3x120+70)	32x(3x185+57)

1) IM10L, IR10L, IM12L, or IR12L

7.2.5 Alternative Cable Sizes for Marine Installations, AFE or GC Modules 525–690 V AC

Table 18: Cable Sizes for AFE or GC Modules 525–690 V AC for Marine Applications (Marine cables according to IEC 60092-352)

Model code	Frame ⁽¹⁾	Mains cable Cu [mm ²]
iC7-60SLxx07-236AE00Fx	Ax10L	2x(3x70)
iC7-60SLxx07-300AE00Fx		2x(3x95)
iC7-60SLxx07-334AE00Fx		3x(3x70)
iC7-60SLxx07-380AE00Fx		3x(3x95)
iC7-60SLxx07-425AE00Fx	Ax12L	3x(3x95)
iC7-60SLxx07-475AE00Fx		3x(3x95)
iC7-60SLxx07-530AE00Fx		4x(3x95)
iC7-60SLxx07-595AE00Fx		4x(3x95)
iC7-60SLxx07-670AE00Fx		5x(3x95)
iC7-60SLxx07-760AE00Fx		5x(3x95)

Table 18: Cable Sizes for AFE or GC Modules 525–690 V AC for Marine Applications (Marine cables according to IEC 60092-352) (continued)

Model code	Frame ⁽¹⁾	Mains cable Cu [mm ²]
iC7-60SLxx07-850AE00Fx	2 x Ax12L	6x(3x95)
iC7-60SLxx07-945AE00Fx		6x(3x95)
iC7-60SLxx07-1040E00Fx		8x(3x95)
iC7-60SLxx07-1230E00Fx		8x(3x95)
iC7-60SLxx07-1325E00Fx		10x(3x95)
iC7-60SLxx07-1500E00Fx		10x(3x95)
iC7-60SLxx07-1700E00Fx	3 x Ax12L	12x(3x95)
iC7-60SLxx07-1800E00Fx		12x(3x95)
iC7-60SLxx07-2000E00Fx		12x(3x95)
iC7-60SLxx07-2250E00Fx		12x(3x95)
iC7-60SLxx07-2500E00Fx	4 x Ax12L	16x(3x95)
iC7-60SLxx07-2650E00Fx		20x(3x95)
iC7-60SLxx07-2940E00Fx		20x(3x95)
iC7-60SLxx07-3120E00Fx	5 x Ax12L	25x(3x95)
iC7-60SLxx07-3600E00Fx		25x(3x95)
iC7-60SLxx07-3900E00Fx	6 x Ax12L	30x(3x95)
iC7-60SLxx07-4320E00Fx		30x(3x95)
iC7-60SLxx07-4750E00Fx	7 x Ax12L	35x(3x95)
iC7-60SLxx07-5040E00Fx		35x(3x95)
iC7-60SLxx07-5400E00Fx	8 x Ax12L	40x(3x95)
iC7-60SLxx07-5750E00Fx		40x(3x95)

1) AM10L, AR10L, AM12L, or AR12L

7.2.6 Alternative Cable Sizes for Marine Installations, INU Modules 525–690 V AC

Table 19: Cable Sizes for INU Modules 525–690 V AC for Marine Applications (Marine cables according to IEC 60092-352)

Model code	Frame ⁽¹⁾	Motor cable Cu [mm ²]
iC7-60SLIN07-170E00Fx	1x10L	2x(3x70)
iC7-60SLIN07-261E00Fx		2x(3x95)
iC7-60SLIN07-325E00Fx		2x(3x95)
iC7-60SLIN07-365E00Fx		3x(3x95)
iC7-60SLIN07-416E00Fx		3x(3x95)

Table 19: Cable Sizes for INU Modules 525–690 V AC for Marine Applications (Marine cables according to IEC 60092-352) (continued)

Model code	Frame ⁽¹⁾	Motor cable Cu [mm ²]
iC7-60SLIN07-465E00Fx	1x12L	3x(3x95)
iC7-60SLIN07-525E00Fx		4x(3x95)
iC7-60SLIN07-590E00Fx		4x(3x95)
iC7-60SLIN07-650E00Fx		4x(3x95)
iC7-60SLIN07-730E00Fx		5x(3x95)
iC7-60SLIN07-820E00Fx		5x(3x95)
iC7-60SLIN07-945E00Fx	2 x 1x12L	6x(3x95)
iC7-60SLIN07-1060E00Fx		8x(3x95)
iC7-60SLIN07-1230E00Fx		8x(3x95)
iC7-60SLIN07-1400E00Fx		10x(3x95)
iC7-60SLIN07-1500E00Fx		10x(3x95)
iC7-60SLIN07-1640E00Fx		10x(3x95)
iC7-60SLIN07-1795E00Fx	3 x 1x12L	12x(3x95)
iC7-60SLIN07-2080E00Fx		15x(3x95)
iC7-60SLIN07-2300E00Fx		15x(3x95)
iC7-60SLIN07-2460E00Fx		18x(3x95)
iC7-60SLIN07-2830E00Fx	4 x 1x12L	20x(3x95)
iC7-60SLIN07-3050E00Fx		20x(3x95)
iC7-60SLIN07-3260E00Fx		20x(3x95)
iC7-60SLIN07-3500E00Fx	5 x 1x12L	25x(3x95)
iC7-60SLIN07-4035E00Fx		25x(3x95)
iC7-60SLIN07-4400E00Fx	6 x 1x12L	30x(3x95)
iC7-60SLIN07-4850E00Fx		30x(3x95)
iC7-60SLIN07-5300E00Fx	7 x 1x12L	35x(3x95)
iC7-60SLIN07-5600E00Fx		35x(3x95)
iC7-60SLIN07-6100E00Fx	8 x 1x12L	40x(3x95)
iC7-60SLIN07-6400E00Fx		40x(3x95)

1) IM10L, IR10L, IM12L, or IR12L

7.2.7 Source Cable Sizes for DC/DC Converter Modules, 640–1100 V DC and 640–1200 V DC

Table 20: DC/DC Converter Module 640–1100 V DC and 640–1200 V DC Source Cable Sizes, IP00/Open Type.

Model code	Frame	1-core cable Cu [mm ²]	3-core cable Cu [mm ²] ⁽¹⁾	4-core cable Cu [mm ²] ⁽²⁾
iC7-60SLDC07-300A	DR10L	3x(1x95)	2x(3x70)	1x(4x70)
iC7-60SLDC07-360A		3x(1x95)	2x(3x70)	1x(4x70)
iC7-60SLDC07-420A		4x(1x95)	2x(3x95)	1x(4x95)
iC7-60SLDC07-480A		4x(1x95)	2x(3x95)	1x(4x95)
iC7-60SLDC07-570A		4x(1x120)	2x(3x120)	1x(4x120)
iC7-60SLDC07-720A	DR12L	5x(1x95)	3x(3x95)	2x(4x70)
iC7-60SLDC07-840A		6x(1x95)	3x(3x95)	2x(4x70)
iC7-60SLDC07-960A		7x(1x95)	3x(3x120)	2x(4x95)
iC7-60SLDC07-1080		7x(1x95)	3x(3x120)	2x(4x95)
iC7-60SLDC07-1200		8x(1x95)	4x(3x120)	2x(4x120)
iC7-60SLDC07-1440	2 x DR12L	10x(1x95)	6x(3x95)	4x(4x70)
iC7-60SLDC07-1680		12x(1x95)	6x(3x95)	4x(4x70)
iC7-60SLDC07-1920		14x(1x95)	6x(3x120)	4x(4x95)
iC7-60SLDC07-2160		14x(1x95)	6x(3x120)	4x(4x95)
iC7-60SLDC07-2400		16x(1x95)	8x(3x120)	4x(4x120)
iC7-60SLDC07-2880	3 x DR12L	21x(1x95)	9x(3x120)	6x(4x95)
iC7-60SLDC07-3240		21x(1x95)	9x(3x120)	6x(4x95)
iC7-60SLDC07-3600		24x(1x95)	12x(3x120)	6x(4x120)
iC7-60SLDC07-3840	4 x DR12L	28x(1x95)	12x(3x120)	8x(4x95)
iC7-60SLDC07-4320		28x(1x95)	12x(3x120)	8x(4x95)
iC7-60SLDC07-4800		32x(1x95)	16x(3x120)	8x(4x120)

1) 3-core cables: Use 2 conductors for 'plus' and 'minus', and a 3rd conductor for PE.

2) 4-core cables: Use 2 conductors for 'plus' and 2 conductors for 'minus'.

7.2.8 Cable Sizes for DC-filter Capacitors

For connecting the minus terminal of the DC-filter capacitor to the DC bus, use copper cable or single wire with at least 1100 V DC voltage, and 90 °C (194 °F) temperature rating. See also [4.5.4 Installing the Cables, DC/DC Converter \(DR10L, DR12L\)](#).

Minimum cable sizes

- DR10L: 16 mm² (AWG 6)
- DR12L: 35 mm² (AWG 2)

The terminal size is M6.

7.3 Fuses

7.3.1 List of Fuse Size Information

This topic lists the links to find the fuse size tables for the system modules.

- [7.3.2 AC Fuses for AFE or GC 525–690 V AC, IP00/Open Type](#)
- [7.3.3 DC Fuses for AFE or GC 640–1200 V DC, IP00/Open Type](#)
- [7.3.4 DC Fuses for INU 640–1200 V DC, IP00/Open Type](#)
- [7.3.5 DC-bus Fuses for DC/DC Converter, IP00/Open Type](#)
- [7.3.6 Source DC+ Fuses for DC/DC Converter, IP00/Open Type](#)
- [7.3.7 Source DC- Fuses for DC/DC Converter, IP00/Open Type](#)

Table 21: Abbreviations Used in the Fuse Tables

Abbreviation	Description
$I_{cp, mr}$	Minimum required prospective short-circuit current at 5 ms pre-arcing time. If there is a short-circuit fault in the common DC bus, a multiplied $I_{cp, mr}$ value is required.
I_L	Nominal current of the drive with low overload (110%). Allows a +10% load variation for 1 minute every 5 minutes.
I_N	Nominal current of the fuse.
U_N	Nominal voltage of the fuse.

7.3.2 AC Fuses for AFE or GC 525–690 V AC, IP00/Open Type

Table 22: AC Fuses for AFE or GC 525–690 V AC, IP00/Open Type

Model code ⁽¹⁾	Frame	Rated current I_L [A]	Number of fuses	Fuse size	Part number	Fuse U_N [V]	Fuse I_N [A]	$I_{cp, mr}$ [A]			
iC7-60SLxx0x-236AE00Fx	Ax10L	236	6	31	PC31UD69V250TF	690	250	2900			
iC7-60SLxx0x-261AE00Fx ⁽²⁾		261									
iC7-60SLxx0x-300AE00Fx		300									
iC7-60SLxx0x-325AE00Fx ⁽²⁾		325			PC31UD69V315TF				690	315	3600
iC7-60SLxx0x-334AE00Fx		334									
iC7-60SLxx0x-380AE00Fx		380									
iC7-60SLxx0x-425AE00Fx	Ax12L	425	3	44	PC44UD75V12CTQ	750	1200	7200			
iC7-60SLxx0x-475AE00Fx		475									
iC7-60SLxx0x-530AE00Fx		530									
iC7-60SLxx0x-595AE00Fx		595									
iC7-60SLxx0x-670AE00Fx		670									
iC7-60SLxx0x-760AE00Fx		760									

Table 22: AC Fuses for AFE or GC 525–690 V AC, IP00/Open Type (continued)

Model code ⁽¹⁾	Frame	Rated current I_L [A]	Number of fuses	Fuse size	Part number	Fuse U_n [V]	Fuse I_n [A]	$I_{cp, mr}$ [A]
iC7-60SLxx0x-850AE00Fx	2 x Ax12L	850	6	44	PC44UD75V12CTQ	750	1200	2x7200
iC7-60SLxx0x-945AE00Fx		945						
iC7-60SLxx0x-1040E00Fx		1040						
iC7-60SLxx0x-1230E00Fx		1230						
iC7-60SLxx0x-1325E00Fx		1325						
iC7-60SLxx0x-1500E00Fx		1500						
iC7-60SLxx0x-1700E00Fx	3 x Ax12L	1700	9	44	PC44UD75V12CTQ	750	1200	3x7200
iC7-60SLxx0x-1800E00Fx		1800						
iC7-60SLxx0x-2000E00Fx		2000						
iC7-60SLxx0x-2250E00Fx		2250						
iC7-60SLxx0x-2500E00Fx	4 x Ax12L	2500	12	44	PC44UD75V12CTQ	750	1200	4x7200
iC7-60SLxx0x-2650E00Fx		2650						
iC7-60SLxx0x-2940E00Fx		2940						
iC7-60SLxx0x-3120E00Fx	5 x Ax12L	3120	15	44	PC44UD75V12CTQ	750	1200	5x7200
iC7-60SLxx0x-3600E00Fx		3600						
iC7-60SLxx0x-3900E00Fx	6 x Ax12L	3900	18	44	PC44UD75V12CTQ	750	1200	6x7200
iC7-60SLxx0x-4320E00Fx		4320						
iC7-60SLxx0x-4750E00Fx	7 x Ax12L	4750	21	44	PC44UD75V12CTQ	750	1200	7x7200
iC7-60SLxx0x-5040E00Fx		5040						
iC7-60SLxx0x-5400E00Fx	8 x Ax12L	5400	24	44	PC44UD75V12CTQ	750	1200	8x7200
iC7-60SLxx0x-5750E00Fx		5750						

1) For example, iC7-60SL3A07-236AE00F4

2) Only for B5 voltage class

7.3.3 DC Fuses for AFE or GC 640–1200 V DC, IP00/Open Type

Table 23: DC Fuses for AFE or GC 640–1200 V DC, IP00/Open Type

Model code ⁽¹⁾	Frame	Rated current I_L [A]	Number of fuses	Fuse size	Part number	Fuse U_n [V]	Fuse I_n [A]	$I_{cp, mr}$ [A]
iC7-60SL3A0x-236AE00Fx	Ax10L	236	2	73	PC73UD13C800TF	1250	800	8900
iC7-60SL3A0x-300AE00Fx		300						
iC7-60SL3A0x-334AE00Fx		334			PC73UD12C900TF	1200	900	10200
iC7-60SL3A0x-380AE00Fx		380						
iC7-60SL3A0x-425AE00Fx	Ax12L	425	4	73	PC73UD13C800TF	1250	800	8900
iC7-60SL3A0x-475AE00Fx		475						
iC7-60SL3A0x-530AE00Fx		530						
iC7-60SL3A0x-595AE00Fx		595			PC73UD12C900TF	1200	900	10200
iC7-60SL3A0x-670AE00Fx		670						
iC7-60SL3A0x-760AE00Fx		760						
iC7-60SL3A0x-850AE00Fx	2 x Ax12L	850	8	73	PC73UD13C800TF	1250	800	8900
iC7-60SL3A0x-945AE00Fx		945						
iC7-60SL3A0x-1040E00Fx		1040						
iC7-60SL3A0x-1230E00Fx		1230			PC73UD12C900TF	1200	900	10200
iC7-60SL3A0x-1325E00Fx		1325						
iC7-60SL3A0x-1500E00Fx		1500						
iC7-60SL3A0x-1700E00Fx	3 x Ax12L	1700	12	73	PC73UD13C800TF	1250	800	8900
iC7-60SL3A0x-1800E00Fx		1800						
iC7-60SL3A0x-2000E00Fx		2000			PC73UD12C900TF	1200	900	10200
iC7-60SL3A0x-2250E00Fx		2250						
iC7-60SL3A0x-2500E00Fx	4 x Ax12L	2500	16	73	PC73UD12C900TF	1200	900	10200
iC7-60SL3A0x-2650E00Fx		2650						
iC7-60SL3A0x-2940E00Fx		2940						
iC7-60SL3A0x-3120E00Fx	5 x Ax12L	3120	20	73	PC73UD12C900TF	1200	900	10200
iC7-60SL3A0x-3600E00Fx		3600						
iC7-60SL3A0x-3900E00Fx	6 x Ax12L	3900	24	73	PC73UD12C900TF	1200	900	10200
iC7-60SL3A0x-4320E00Fx		4320						
iC7-60SL3A0x-4750E00Fx	7 x Ax12L	4750	28	73	PC73UD12C900TF	1200	900	10200
iC7-60SL3A0x-5040E00Fx		5040						

Table 23: DC Fuses for AFE or GC 640–1200 V DC, IP00/Open Type (continued)

Model code ⁽¹⁾	Frame	Rated current I_L [A]	Number of fuses	Fuse size	Part number	Fuse U_n [V]	Fuse I_n [A]	$I_{cp, mr}$ [A]
iC7-60SL3A0x-5400E00Fx	8 x Ax12L	5400	32	73	PC73UD12C900TF	1200	900	10200
iC7-60SL3A0x-5750E00Fx		5750						

1) For example, iC7-60SL3A07-236AE00F4

7.3.4 DC Fuses for INU 640–1200 V DC, IP00/Open Type

Table 24: DC Fuses for INU 640–1200 V DC, IP00/Open Type

Model code ⁽¹⁾	Frame	Rated current I_L [A]	Number of fuses	Fuse size	Part number	Fuse U_n [V]	Fuse I_n [A]	$I_{cp, mr}$ [A]
iC7-60SLIN0x-170AE00Fx	lx10L	170	2	73	PC73UD13C630TF	1250	630	5900
iC7-60SLIN0x-206AE00Fx ⁽²⁾		206						
iC7-60SLIN0x-208AE00Fx		208						
iC7-60SLIN0x-245AE00Fx ⁽²⁾		245						
iC7-60SLIN0x-261AE00Fx		261			PC73UD13C800TF	800	8900	
iC7-60SLIN0x-302AE00Fx ⁽²⁾		302						
iC7-60SLIN0x-325AE00Fx		325						
iC7-60SLIN0x-365AE00Fx		365						
iC7-60SLIN0x-385AE00Fx ⁽²⁾		385						
iC7-60SLIN0x-416AE00Fx		416						
iC7-60SLIN0x-465AE00Fx	lx12L	465	4	73	PC73UD13C800TF	1250	800	8900
iC7-60SLIN0x-525AE00Fx		525						
iC7-60SLIN0x-590AE00Fx		590						
iC7-60SLIN0x-650AE00Fx		650			PC73UD12C900TF	1200	900	10200
iC7-60SLIN0x-730AE00Fx		730						
iC7-60SLIN0x-820AE00Fx		820						
iC7-60SLIN0x-945AE00Fx	2 x lx12L	945	8	73	PC73UD13C800TF	1250	800	8900
iC7-60SLIN0x-1060E00Fx		1060						
iC7-60SLIN0x-1230E00Fx		1230						
iC7-60SLIN0x-1400E00Fx		1400			PC73UD12C900TF	1200	900	10200
iC7-60SLIN0x-1500E00Fx		1500						
iC7-60SLIN0x-1640E00Fx		1640						

Table 24: DC Fuses for INU 640–1200 V DC, IP00/Open Type (continued)

Model code ⁽¹⁾	Frame	Rated current I_L [A]	Number of fuses	Fuse size	Part number	Fuse U_n [V]	Fuse I_n [A]	$I_{cp, mr}$ [A]
iC7-60SLIN0x-1795E00Fx	3 x lx12L	1795	12	73	PC73UD13C800TF	1250	800	8900
iC7-60SLIN0x-2080E00Fx		2080			PC73UD12C900TF	1200	900	10200
iC7-60SLIN0x-2300E00Fx		2300						
iC7-60SLIN0x-2500E00Fx		2500						
iC7-60SLIN0x-2830E00Fx	4 x lx12L	2830	16	73	PC73UD12C900TF	1200	900	10200
iC7-60SLIN0x-3050E00Fx		3050						
iC7-60SLIN0x-3260E00Fx		3260						
iC7-60SLIN0x-3500E00Fx	5 x lx12L	3500	20	73	PC73UD12C900TF	1200	900	10200
iC7-60SLIN0x-4035E00Fx		4035						
iC7-60SLIN0x-4400E00Fx	6 x lx12L	4400	24	73	PC73UD12C900TF	1200	900	10200
iC7-60SLIN0x-4850E00Fx		4850						
iC7-60SLIN0x-5300E00Fx	7 x lx12L	5300	28	73	PC73UD12C900TF	1200	900	10200
iC7-60SLIN0x-5600E00Fx		5600						
iC7-60SLIN0x-6100E00Fx	8 x lx12L	6100	32	73	PC73UD12C900TF	1200	900	10200
iC7-60SLIN0x-6400E00Fx		6400						

1) For example, iC7-60SLIN07-140AE00F4

2) Only for B5 voltage class

7.3.5 DC-bus Fuses for DC/DC Converter, IP00/Open Type

Table 25: DC-bus Fuses for DC/DC Converter, Voltage Classes B5 and 07, IP00/Open Type

Model code ⁽¹⁾	Frame	Rated current (I_L) [A]	Number of fuses	Fuse size	Part number (Mersen)	Fuse U_n [V]	Fuse I_n [A]	$I_{cp, mr}$ [A]
iC7-60SLDCxx-300AE00F4	DR10L	300	2	73	PC73UD13C630TF	1250	630	5900
iC7-60SLDCxx-360AE00F4		360	2					
iC7-60SLDCxx-420AE00F4		420	2	73	PC73UD13C800TF	1250	800	8900
iC7-60SLDCxx-480AE00F4		480	2	73	PC73UD12C900TF	1200	900	10200
iC7-60SLDCxx-570AE00F4		570	2	73	PC73UD12C900TF	1200	900	10200

Table 25: DC-bus Fuses for DC/DC Converter, Voltage Classes B5 and 07, IP00/Open Type (continued)

Model code ⁽¹⁾	Frame	Rated current (I _L) [A]	Number of fuses	Fuse size	Part number (Mersen)	Fuse U _n [V]	Fuse I _n [A]	I _{cp, mr} [A]
iC7-60SLDCxx-720AE00F4	DR12L	720	4	73	PC73UD13C630TF	1250	630	5900
iC7-60SLDCxx-840AE00F4		840	4	73	PC73UD13C800TF	1250	800	8900
iC7-60SLDCxx-960AE00F4		960	4					
iC7-60SLDCxx-1080E00F4		1080	4	73	PC73UD12C900TF	1200	900	10200
iC7-60SLDCxx-1200E00F4		1200	4					
iC7-60SLDCxx-1440E00F4	2 x DR12L	1440	8	73	PC73UD13C630TF	1250	630	5900
iC7-60SLDCxx-1680E00F4		1680	8	73	PC73UD13C800TF	1250	800	8900
iC7-60SLDCxx-1920E00F4		1920	8					
iC7-60SLDCxx-2160E00F4		2160	8	73	PC73UD12C900TF	1200	900	10200
iC7-60SLDCxx-2400E00F4		2400	8					
iC7-60SLDCxx-2880E00F4	3 x DR12L	2880	12	73	PC73UD13C800TF	1250	800	8900
iC7-60SLDCxx-3240E00F4		3240	12	73	PC73UD12C900TF	1200	900	10200
iC7-60SLDCxx-3600E00F4		3600	12					

1) xx = B5 or 07

7.3.6 Source DC+ Fuses for DC/DC Converter, IP00/Open Type

Table 26: Source DC+ Fuses for DC/DC Converter, Voltage Classes B5 and 07, IP00/Open Type

Model code ⁽¹⁾	Frame	Rated current (I _L) [A]	Number of fuses	Fuse size	Part number (Mersen)	Fuse U _n [V]	Fuse I _n [A]	I _{cp, mr} [A]
iC7-60SLDCxx-300AE00F4	DR10L	300	3	72	D72SG120V250QF	1200	250	1600
iC7-60SLDCxx-360AE00F4		360	3					
iC7-60SLDCxx-420AE00F4		420	3					
iC7-60SLDCxx-480AE00F4	DR10L	480	3	72	D72SG120V315QF	1200	315	2200
iC7-60SLDCxx-570AE00F4		570	3					
iC7-60SLDCxx-720AE00F4	DR12L	720	3	272	D272SG120V500QF	1200	500	3100
iC7-60SLDCxx-840AE00F4		840	3					
iC7-60SLDCxx-960AE00F4		960	3					
iC7-60SLDCxx-1080E00F4		1080	3	272	D272SG120V630QF	1200	630	4400
iC7-60SLDCxx-1200E00F4		1200	3					

Table 26: Source DC+ Fuses for DC/DC Converter, Voltage Classes B5 and 07, IP00/Open Type (continued)

Model code ⁽¹⁾	Frame	Rated current (I _L) [A]	Number of fuses	Fuse size	Part number (Mersen)	Fuse U _n [V]	Fuse I _n [A]	I _{cp, mr} [A]
iC7-60SLDCxx-1440E00F4	2 x DR12L	1440	6	272	D272SG120V500QF	1200	500	2x3100
iC7-60SLDCxx-1680E00F4		1680	6					
iC7-60SLDCxx-1920E00F4		1920	6					
iC7-60SLDCxx-2160E00F4		2160	6	272	D272SG120V630QF	1200	630	2x4400
iC7-60SLDCxx-2400E00F4		2400	6					
iC7-60SLDCxx-2880E00F4	3 x DR12L	2880	9	272	D272SG120V500QF	1200	500	3x3100
iC7-60SLDCxx-3240E00F4		3240	9					
iC7-60SLDCxx-3600E00F4		3600	9					

1) xx = B5 or 07

7.3.7 Source DC- Fuses for DC/DC Converter, IP00/Open Type

Table 27: Source DC- Fuses for DC/DC Converter, Voltage Classes B5 and 07, IP00/Open Type

Model code ⁽¹⁾	Frame	Rated current (I _L) [A]	Number of fuses	Fuse size	Part number (Mersen)	Fuse U _n [V]	Fuse I _n [A]	I _{cp, mr} [A]
iC7-60SLDCxx-300AE00F4	DR10L	300	1	73	PC73UD13C630TF	1250	630	5900
iC7-60SLDCxx-360AE00F4		360	1					
iC7-60SLDCxx-420AE00F4		420	1	73	PC73UD13C800TF	1250	800	8900
iC7-60SLDCxx-480AE00F4		480	1	73	PC73UD12C900TF	1200	900	10200
iC7-60SLDCxx-570AE00F4		570	1	73				
iC7-60SLDCxx-720AE00F4	DR12L	720	2	73	PC73UD13C630TF	1250	630	5900
iC7-60SLDCxx-840AE00F4		840	2					
iC7-60SLDCxx-960AE00F4		960	2					
iC7-60SLDCxx-1080E00F4		1080	2	73	PC73UD12C900TF	1200	900	10200
iC7-60SLDCxx-1200E00F4		1200	2					
iC7-60SLDCxx-1440E00F4	2 x DR12L	1440	4	73	PC73UD13C630TF	1250	630	5900
iC7-60SLDCxx-1680E00F4		1680	4					
iC7-60SLDCxx-1920E00F4		1920	4					
iC7-60SLDCxx-2160E00F4		2160	4	73	PC73UD12C900TF	1200	900	10200
iC7-60SLDCxx-2400E00F4		2400	4					

Table 27: Source DC- Fuses for DC/DC Converter, Voltage Classes B5 and 07, IP00/Open Type (continued)

Model code ⁽¹⁾	Frame	Rated current (I _L) [A]	Number of fuses	Fuse size	Part number (Mersen)	Fuse U _n [V]	Fuse I _n [A]	I _{cp, mr} [A]
iC7-60SLDCxx-2880E00F4	3 x DR12L	2880	6	73	PC73UD13C800TF	1250	800	8900
iC7-60SLDCxx-3240E00F4		3240	6	73	PC73UD12C900TF	1200	900	10200
iC7-60SLDCxx-3600E00F4		3600	6					

1) xx = B5 or 07

Danfoss Drives Oy
Runsorintie 7
FIN-65380 Vaasa
drives.danfoss.com

.....
Any information, including, but not limited to information on selection of product, its application or use, product design, weight, dimensions, capacity or any other technical data in product manuals, catalog descriptions, advertisements, etc. and whether made available in writing, orally, electronically, online or via download, shall be considered informative, and is only binding if and to the extent, explicit reference is made in a quotation or order confirmation. Danfoss cannot accept any responsibility for possible errors in catalogs, brochures, videos and other material. Danfoss reserves the right to alter its products without notice. This also applies to products ordered but not delivered provided that such alterations can be made without changes to form, fit or function of the product. All trademarks in this material are property of Danfoss A/S or Danfoss group companies. Danfoss and the Danfoss logo are trademarks of Danfoss A/S. All rights reserved.
.....

