

Software Change Note

Product: Vacon NXS series
Software type: Water Solutions application package
New software id: ASFIG100V110
Old software id: ASFIG100V109

Mal-functions in the old software:

1. ASFIFF24V109, ALC:
The drive didn't activate warning/fault if the 4mA signal fell when the drive was in SLEEP mode

Changes in the new software:

1. The above-mentioned bugs are fixed.

Field update:

It is recommended to update the application if the above-mentioned malfunctions are faced.

System software requirements:

NXS00001V150
NXP00002V144

Manual:

UD861

NOTE!